



Graphite v10 Quick Reference Card

Graphite v10 SP0 - [Untitled 1]

File Edit Layout Arrange Pen Text Dimension Views 3D Utilities Window Help

Select: Select [Shift = Extend, Ctrl = Copy]

Triad (Message Line)

Selection Tools

Line Tools

Arc Tools

Circle Tools

Ellipse Tools

Poligone Tools

Spline Tools

Text Tools

Dimension Tools

Fillet and Chamfer Tools

Trim Tools

Transform and Duplicate Tools

View Tools

Miscellaneous Tools

Bill of Materials

Navigator Palette

Trackcube/Trackball

Dimensions Palette

General Palette

Pen Style Palette

Drafting Assistant Notation (midpoint)

Layer Group Window

Layer Indicator

Pointer Locator

Status Line

Edit Objects

1 line

Locked: unlocked

Layer: Construction

Text: Black

Pattern: Solid

Weight: .002"

Control Pts: hidden

Point 1.x: -2.875

Point 1.y: 6.437

Point 1.z: 0

Point 2.x: -2.042

Point 2.y: 6.437

Point 2.z: 0

Length: .833

Angle: 0°

Arrowhead: none

Close Apply

Edit Objects Window

Layers

GENERAL VIEW Conform

< Layer1 Sort

< ✓ Construction New

< Dimension Delete

< Constraints Hide

Rename Layer: Construction Set Layer

Rename

X: .063 Y: -1.594 Z: 0 IX: 1.062 IY: -.719 IZ: 0 1.283 A: -34° 4' 3"

Layer1 .594 -1.953 0



Graphite v10 Quick Reference Card

Special Characters

Special drafting symbols and characters are accessed from the keyboard. For a complete list of these characters see Appendix B in the User Guide.

Windows

Hold down the ALT key and type the desired numeric code:

Mark	Key Combination
°	ALT 0176
∅	ALT 0216
±	ALT 0177

Macintosh

Hold down the Option key and type the desired numeric code:

Mark	Key Combination
é	OPTION+e then letter to be accented
è	OPTION+` then letter to be accented
ñ	OPTION+n then letter to be accented
ü	OPTION+u then letter to be accented

The following list includes common symbols which are available in all fonts.

Mark	Key Combination
°	OPTION+SHIFT 8
∅	OPTION+O (letter or number)
±	OPTION+SHIFT =

